

Summary of the Water Testing Results

School	Source Number on the Site Map	Sample Location	Draw Number	Lead Sample Result ppb	IDPH Notification Level 5 ppb	EPA Action Level 15 ppb	Action Taken
Algonquin	32	Classroom 134 - Sink	1	5.13	x		Flushing Program
			2	5.86	x		
Algonquin	27	Classroom 153 - Sink	1	57.2	x	x	Flushing Program
			2	7.96	x		
Algonquin	24	Classroom 155 - Sink	1	22.3	x	x	Flushing Program
			2	4.41			
Algonquin	14	Classroom 156 - Sink	1	70.5	x	x	Flushing Program
			2	4.48			
Algonquin	16	Classroom 156 - Sink	1	2.63			Flushing Program
			2	33.1	x	x	
Algonquin	23	Classroom 157 - Sink	1	<2.00			Flushing Program
			2	5.87	x	x	
Algonquin	20	Classroom 158 - Sink	1	74.3	x	x	Flushing Program
			2	2.24			
Algonquin	21	Classroom 158 - Sink	1	<2.00			Flushing Program
			2	19.9	x	x	
Central	26	Hallway Hand wash Sink	1	10.3	x		Flushing Program
			2	6.08	x		
Central	29	Hallway Hand wash Sink	1	6.6	x		Flushing Program
			2	3.69			
Chippewa	3	Classroom 127 - Sink	1	12	x		Flushing Program
			2	<2.00			
Chippewa	9	Classroom 142 - Sink	1	129	x	x	Flushing Program
			2	2.04			
Chippewa	11	Classroom 147 - Sink	1	51.7	x	x	Flushing Program
			2	<2.00			
Chippewa	32	Classroom 174 - Sink	1	7.76	x		Flushing Program
			2	<2.00			
Cumberland	2	Classroom 125 - Sink	1	8.35	x		Flushing Program
			2	<2.00			

School	Source Number on the Site Map	Sample Location	Draw Number	Lead Sample Result ppb	IDPH Notification Level 5 ppb	EPA Action Level 15 ppb	Action Taken
Forest/ELC	44	Classroom 229 - Tall Sink	1	5.12	x		Flushing Program
			2	<2.00			
Iroquois	3	Girls Locker Room Water Fountain	1	11.2	x		The water fountain has been removed.
			2	5.46	x		
Iroquois	13	Classroom 123 - South Sink	1	10.5	x		A new faucet has been installed. Flushing Program
			2	5.24	x		
These repairs were made prior to the start of school in July.							
North	11	Classroom 139 - Sink	1	227	x		A new faucet has been installed. Flushing Program
			2	11.8	x		
Orchard Place	No samples exceeded the IDPH reporting level						
Plainfield	1	Classroom 121 - Sink	1	5.69	x		A new faucet has been installed. Flushing Program
			2	<2.00			
Plainfield	6	Classroom 124 - Sink	1	5.52	x		A new faucet has been installed. Flushing Program
			2	<2.00			
Plainfield	11	Hallway Water Fountain	1	9.62	x		The water fountain has been removed.
			2	4.21			
Plainfield	22	Kitchen Sink	1	12.6	x		A new faucet has been installed. Flushing Program
			2	<2.00			

School	Source Number on the Site Map	Sample Location	Draw Number	Lead Sample Result ppb	IDPH Notification Level 5 ppb	EPA Action Level 15 ppb	Action Taken
Plainfield	23	Kitchen Sink	1	98.9	x	x	A new faucet has been installed. Flushing Program
			2	<2.00			
Plainfield	24	Kitchen Sink	1	41.1	x		A new faucet has been installed. Flushing Program
			2	9.03	x	x	
These repairs were made prior to the start of summer school in July.							
South	4	Kitchen Sink	1	57.7	x	x	A new faucet has been installed. Flushing Program
			2	9.54	x		
Terrace	No samples exceeded the IDPH reporting level						